## HAER ALA 45-HUVI.Y 7I-

## HISTORIC AMERICAN ENGINEERING RECORD

## INDEX TO PHOTOGRAPHS

MARSHALL SPACE FLIGHT CENTER,
EAST TEST AREA,
COMPONENTS TEST LABORATORY
(Marshall Space Flight Center,
Building No. 4583)
Redstone Arsenal
Huntsville Vicinity
Madison County
Alabama

HAER No. AL-129-I

Jet Lowe, Photographer, 1996.

AL-129-1-1	CATCH BASINS, TURBINE TESTING AREA, AND PUMP TESTING TOWER.
AL-129-I-2	VIEW SOUTH, FROM LEFT TO RIGHT COMPONENTS TEST LAB SHOWING TEST BAYS AND CATCH BASINS
AL-129-I-3	VIEW LOOKING NORTH, COMPONENTS TEST LABORATORY, DYNAMIC TEST FACILITY (SATURN V IN BACKGROUND)
AL-129-I-4	VIEW SOUTHWEST COMPONENTS TEST LAB TEST BAY DETAIL SHOWING EMERGENCY SHOWER, AND EYEWASH, AND OBSERVATION WINDOW. STORAGE TANKS ON ROOF.

Historic Photograph AL-129-I-5: Date, Photographer and the source of the photographs, if known, are noted in the caption.

AL-129-I-5 AERIAL PHOTO OF THE COMPONENTS TEST LABORATORY DURING THE CONSTRUCTION OF THE EAST TEST AREA.

1955, FRED ORDWAY COLLECTION, U.S. SPACE AND ROCKET CENTER, HUNTSVILLE, AL